

Building Instructions Step										Penalties
Page	Mismatch Type	Mismatch Specific	Occurrences	Color	Part mismatched					
Name: Jan Mudrack										114
Nickname: laix-engineering										
Country: D										
Submission Date / Time: 2013-11-23 / 19:52										
Submission entry order: 1										
Digital File Type: LDD										
Annotations:										
26.4	30	Missing	Part	1	4265c "Light Bluish Gray Technic Bush 1/2 Smooth"					5
26.3	29	Wrong	Part	1	32209 "Dark Bluish Gray Technic, Axle 5.5 with Stop"					3
24.8	27	Misplacement	Orientation	1	60483 "Light Bluish Gray Technic, Liftarm 1 x 2 Thick with Pin Hole and Axle Hole"					3
24.7	26	Misplacement	Orientation	1	60483 "Light Bluish Gray Technic, Liftarm 1 x 2 Thick with Pin Hole and Axle Hole"					3
20.4	18	Wrong	Part	1	3713 "Light Bluish Gray Technic Bush"					3
20.3	18	Wrong	Part	1	32209 "Dark Bluish Gray Technic, Axle 5.5 with Stop"					3
15	15	Wrong	Part	1	43093 "Blue Technic, Axle Pin with Friction Ridges Lengthwise"					3
		Wrong	Part	1	6632 "Black Technic, Liftarm 1 x 3 Thin"					5
		Missing	Part	1	6632 "Black Technic, Liftarm 1 x 3 Thin"					5
14.4	14	Missing	Part	2	43093 "Blue Technic, Axle Pin with Friction Ridges Lengthwise"					10
14.3		Extra	Part	2	2780 "Black Technic, Pin with Friction Ridges Lengthwise WITH Center Slots"					6
14.2		Missing	Part	2	32184 "Black Technic, Axle and Pin Connector Perpendicular 3L with Center Pin Hole"					10
13.10	13	Wrong	Color (Visible)	1	6536 "White Technic, Axle and Pin Connector Perpendicular"	LBG	instead of	White		3
13.9	12	Missing	Part	1	3713 "Light Bluish Gray Technic Bush"					5
		Wrong	Part	1	87083 "Dark Bluish Gray Technic, Axle 4 with Stop"					3
13.4	10	Wrong	Part	1	2780 "Black Technic, Pin with Friction Ridges Lengthwise WITH Center Slots"					3
		Wrong	Part	1	6558 "Blue Technic, Pin Long with Friction Ridges Lengthwise"					3
13.1	9	Wrong	Part	1	43093 "Blue Technic, Axle Pin with Friction Ridges Lengthwise"					3
		Wrong	Part	1	6632 "Black Technic, Liftarm 1 x 3 Thin"					3
		Missing	Part	1	6632 "Black Technic, Liftarm 1 x 3 Thin"					5
7	6	Wrong	Part	2	2825 "Light Bluish Gray Technic, Liftarm 1 x 4 Thin with Stud Connector"					6
		Misplacement	Deviation	2	32140 "Black Technic, Liftarm 2 x 4 L-Shape Thick"					3
6	6	Missing	Part	1	43093 "Blue Technic, Axle Pin with Friction Ridges Lengthwise"					5
		Missing	Part	1	32054 "Light Bluish Gray Technic, Pin Long with Friction Ridges Lengthwise and Stop Bush"					5
5	5	Missing	Part	1	4519 "Light Bluish Gray Technic, Axle 3"					5
2	3	Missing	Part	1	32184 "Black Technic, Axle and Pin Connector Perpendicular 3L with Center Pin Hole"					5
Name: Miha Maraž										79
Nickname: MjkiSpajki										
Country: SI										
Submission Date / Time: 2013-11-23 / 19:55										
Submission entry order: 2										
Digital File Type: LDD										
Annotations:										
26.4	30	Missing	Part	1	4265c "Light Bluish Gray Technic Bush 1/2 Smooth"					5
26.3	29	Wrong	Part	1	32209 "Dark Bluish Gray Technic, Axle 5.5 with Stop"					3
14.4	14	Missing	Part	2	43093 "Blue Technic, Axle Pin with Friction Ridges Lengthwise"					10
14.3		Extra	Part	2	2780 "Black Technic, Pin with Friction Ridges Lengthwise WITH Center Slots"					6
14.2		Wrong	Part	2	32184 "Black Technic, Axle and Pin Connector Perpendicular 3L with Center Pin Hole"					6
13.10	13	Wrong	Color (Visible)	1	6536 "White Technic, Axle and Pin Connector Perpendicular"	LBG	instead of	White		3
13.9	12	Wrong	Part	1	87083 "Dark Bluish Gray Technic, Axle 4 with Stop"					3
13.4	10	Wrong	Part	1	6558 "Blue Technic, Pin Long with Friction Ridges Lengthwise"					3
7	6	Wrong	Part	2	2825 "Light Bluish Gray Technic, Liftarm 1 x 4 Thin with Stud Connector"					6
		Extra	Part	1	32140 "Black Technic, Liftarm 2 x 4 L-Shape Thick"					3
		Extra	Part	1	32052 "Red Technic, Axle 2 Notched"					3
		Extra	Part	1	60483 "Black Gray Technic, Liftarm 1 x 2 Thick with Pin Hole and Axle Hole"					3
		Extra	Part	1	6558 "Blue Technic, Pin Long with Friction Ridges Lengthwise"					3
		Extra	Part	2	6536 "Light Bluish Gray Technic, Axle and Pin Connector Perpendicular"					6
		Extra	Part	2	6558 "Blue Technic, Pin Long with Friction Ridges Lengthwise"					6
6	6	Missing	Part	1	43093 "Blue Technic, Axle Pin with Friction Ridges Lengthwise"					5
		Missing	Part	1	32054 "Light Bluish Gray Technic, Pin Long with Friction Ridges Lengthwise and Stop Bush"					5
Name: Han Crielaard										92
Nickname: Designer-Han										
Country: NL										
Submission Date / Time: 2013-11-23 / 22:44										
Submission entry order: 3										
Digital File Type: LDraw / MPD										
Annotations:										
26.4	30	Missing	Part	1	4265c "Light Bluish Gray Technic Bush 1/2 Smooth"					5
26.3	29	Wrong	Part	1	32209 "Dark Bluish Gray Technic, Axle 5.5 with Stop"					3
24.8	27	Misplacement	Orientation	1	60483 "Light Bluish Gray Technic, Liftarm 1 x 2 Thick with Pin Hole and Axle Hole"					3
24.7	26	Misplacement	Orientation	1	60483 "Light Bluish Gray Technic, Liftarm 1 x 2 Thick with Pin Hole and Axle Hole"					3
23.2	24	Missing	Part	1	4265c "Light Bluish Gray Technic Bush 1/2 Smooth"					5
22.5	23	Missing	Part	1	4265c "Light Bluish Gray Technic Bush 1/2 Smooth"					3
20.4	18	Wrong	Part	2	3713 "Light Bluish Gray Technic Bush"					10
14.4	14	Missing	Part	2	43093 "Blue Technic, Axle Pin with Friction Ridges Lengthwise"					10
14.2		Wrong	Part	2	32184 "Black Technic, Axle and Pin Connector Perpendicular 3L with Center Pin Hole"					6
13.10	13	Wrong	Color (Visible)	1	6536 "White Technic, Axle and Pin Connector Perpendicular"	LBG	instead of	White		3
13.9	12	Missing	Part	1	3713 "Light Bluish Gray Technic Bush"					5
		Wrong	Part	1	87083 "Dark Bluish Gray Technic, Axle 4 with Stop"					3
13.5	11	Wrong	Part	1	42003 "Light Bluish Gray Technic, Axle and Pin Connector Perpendicular 3L with 2 Pin Holes"					3
13.4	10	Wrong	Part	1	6558 "Blue Technic, Pin Long with Friction Ridges Lengthwise"					3
7	6	Extra	Part	1	4519 "Light Bluish Gray Technic, Axle 3"					3
6	6	Wrong	Part	1	43093 "Blue Technic, Axle Pin with Friction Ridges Lengthwise"					3
		Missing	Part	1	32054 "Light Bluish Gray Technic, Pin Long with Friction Ridges Lengthwise and Stop Bush"					5
3	4	Misplacement	Orientation	1	32526 "Light Bluish Gray Technic, Liftarm 3 x 5 L-Shape Thick"					3
		Extra	Part	1	60483 "Black Technic, Liftarm 1 x 2 Thick with Pin Hole and Axle Hole"					3
2	3	Extra	Part	1	32140 "Black Technic, Liftarm 2 x 4 L-Shape Thick"					3
		Extra	Part	1	4519 "Light Bluish Gray Technic, Axle 3"					3
		Wrong	Part	1	32184 "Black Technic, Axle and Pin Connector Perpendicular 3L with Center Pin Hole"					3
1		Misplacement	Orientation	1	32526 "Light Bluish Gray Technic, Liftarm 3 x 5 L-Shape Thick"					3
		Extra	Part	1	60483 "Black Technic, Liftarm 1 x 2 Thick with Pin Hole and Axle Hole"					3
Name: Owen Dive										86
Nickname: Captainowie										
Country: AU										
Submission Date / Time: 2013-11-24 / 06:24										
Submission entry order: 4										
Digital File Type: SR 3D										
Annotations:										
27.1	32	Missing	Part	1	87082 "Black Technic, Pin Long with Friction Ridges Lengthwise and Center Pin Hole"					5
26.4	30	Missing	Part	1	4265c "Light Bluish Gray Technic Bush 1/2 Smooth"					5
26.3	29	Wrong	Part	1	32209 "Dark Bluish Gray Technic, Axle 5.5 with Stop"					3
26.1	28	Wrong	Part	1	87083 "Dark Bluish Gray Technic, Axle 4 with Stop"					3
23.2	24	Wrong	Part	1	4265c "Light Bluish Gray Technic Bush 1/2 Smooth"					3
22.5	23	Wrong	Part	1	4265c "Light Bluish Gray Technic Bush 1/2 Smooth"					3
20.4	18	Missing	Part	1	3713 "Light Bluish Gray Technic Bush"					5
20.3		Wrong	Part	1	32209 "Dark Bluish Gray Technic, Axle 5.5 with Stop"					3
18	17	Wrong	Part	2	32054 "Light Bluish Gray Technic, Pin Long with Friction Ridges Lengthwise and Stop Bush"					6
		Extra	Part	1	32316 "White Technic Beam 5"					3
15	15	Wrong	Part	1	6632 "Black Technic, Liftarm 1 x 3 Thin"					3
		Missing	Part	1	6632 "Black Technic, Liftarm 1 x 3 Thin"					5
		Extra	Part	2	2780 "Black Technic, Pin with Friction Ridges Lengthwise WITH Center Slots"					6
14.4	14	Missing	Part	2	43093 "Blue Technic, Axle Pin with Friction Ridges Lengthwise"					10
14.2		Wrong	Part	2	32184 "Black Technic, Axle and Pin Connector Perpendicular 3L with Center Pin Hole"					6

Building Instructions Step										
Page	Mismatch Type	Mismatch Specific	Occurrences	Color	Part mismatched					Penalties
13.10	13	Wrong	Color (Visible)	1	6536 "White Technic, Axle and Pin Connector Perpendicular"	LBG	instead of	White		3
13.9	12	Missing	Part	1	3713 "Light Bluish Gray Technic Bush"					5
		Wrong	Part	1	87083 "Dark Bluish Gray Technic, Axle 4 with Stop"					3
13.6		Wrong	Part	1	32140 "Black Technic, Liftarm 2 x 4 L-Shape Thick"					3
		Extra	Part	1	60483 "Black Technic, Liftarm 1 x 2 Thick with Pin Hole and Axle Hole"					3
Too much differences to proceed counting mismatches from this point.										

Name:	Gabriel Leite	82
Nickname:		
Country:	BR	
Submission Date / Time:	2013-11-24 / 07:53	
Submission entry order:	5	
Digital File Type	LDD	
Annotations:		

26.4	30	Missing	Part	1	4265c "Light Bluish Gray Technic Bush 1/2 Smooth"					5
26.3	29	Wrong	Part	1	32209 "Dark Bluish Gray Technic, Axle 5.5 with Stop"					3
14.4	14	Missing	Part	2	43093 "Blue Technic, Axle Pin with Friction Ridges Lengthwise"					10
14.3		Extra	Part	2	2780 "Black Technic, Pin with Friction Ridges Lengthwise WITH Center Slots"					6
14.2		Wrong	Part	2	32184 "Black Technic, Axle and Pin Connector Perpendicular 3L with Center Pin Hole"					6
13.10	13	Wrong	Color (Visible)	1	6536 "White Technic, Axle and Pin Connector Perpendicular"	LBG	instead of	White		3
13.9	12	Wrong	Part	1	3713 "Light Bluish Gray Technic Bush"					3
		Misplacement	Deviation	1	87083 "Dark Bluish Gray Technic, Axle 4 with Stop"					3
13.5	11	Wrong	Part	1	42003 "Light Bluish Gray Technic, Axle and Pin Connector Perpendicular 3L with 2 Pin Holes"					3
13.4	10	Wrong	Part	1	6558 "Blue Technic, Pin Long with Friction Ridges Lengthwise"					3
7	6	Misplacement	Deviation	2	2825 "Light Bluish Gray Technic, Liftarm 1 x 4 Thin with Stud Connector"					6
		Wrong	Part	1	32140 "Black Technic, Liftarm 2 x 4 L-Shape Thick"					3
		Extra	Part	1	11478 "Black Technic, Liftarm 1 x 5 Thin with Axle Holes on Ends"					3
		Extra	Part	1	4519 "Light Bluish Gray Technic, Axle 3"					3
6	6	Missing	Part	1	43093 "Blue Technic, Axle Pin with Friction Ridges Lengthwise"					5
		Missing	Part	1	32054 "Light Bluish Gray Technic, Pin Long with Friction Ridges Lengthwise and Stop Bush"					5
5	5	Extra	Part	1	4519 "Light Bluish Gray Technic, Axle 3"					3
		Extra	Part	2	41677 "Black Technic, Liftarm 1 x 2 Thin"					6
2	3	Wrong	Part	1	32184 "Black Technic, Axle and Pin Connector Perpendicular 3L with Center Pin Hole"					3

Name:	Florian Riedl	102
Nickname:	Balrog	
Country:	D	
Submission Date / Time:	2013-11-24 / 12:38	
Submission entry order:	6	
Digital File Type	LDD	
Annotations:		

27.1	32	Missing	Part	1	87082 "Black Technic, Pin Long with Friction Ridges Lengthwise and Center Pin Hole"					5
26.4	30	Missing	Part	1	4265c "Light Bluish Gray Technic Bush 1/2 Smooth"					5
26.3	29	Wrong	Part	1	32209 "Dark Bluish Gray Technic, Axle 5.5 with Stop"					3
26.1	28	Wrong	Part	1	87083 "Dark Bluish Gray Technic, Axle 4 with Stop"					3
24.8	27	Misplacement	Orientation	1	60483 "Light Bluish Gray Technic, Liftarm 1 x 2 Thick with Pin Hole and Axle Hole"					3
24.7	26	Misplacement	Orientation	1	60483 "Light Bluish Gray Technic, Liftarm 1 x 2 Thick with Pin Hole and Axle Hole"					3
20.4	18	Wrong	Part	1	3713 "Light Bluish Gray Technic Bush"					3
18	17	Missing	Part	2	32054 "Light Bluish Gray Technic, Pin Long with Friction Ridges Lengthwise and Stop Bush"					10
15	15	Wrong	Part	1	43093 "Blue Technic, Axle Pin with Friction Ridges Lengthwise"					3
		Wrong	Part	1	6632 "Black Technic, Liftarm 1 x 3 Thin"					3
		Missing	Part	1	6632 "Black Technic, Liftarm 1 x 3 Thin"					3
14.4	14	Wrong	Part	2	43093 "Blue Technic, Axle Pin with Friction Ridges Lengthwise"					6
14.3		Extra	Part	4	2780 "Black Technic, Pin with Friction Ridges Lengthwise WITH Center Slots"					12
14.2		Wrong	Part	2	32184 "Black Technic, Axle and Pin Connector Perpendicular 3L with Center Pin Hole"					6
14.1		Extra	Part	2	43093 "Blue Technic, Axle Pin with Friction Ridges Lengthwise"					6
13.10	13	Wrong	Color (Visible)	1	6536 "White Technic, Axle and Pin Connector Perpendicular"	LBG	instead of	White		3
13.9	12	Missing	Part	1	3713 "Light Bluish Gray Technic Bush"					5
		Wrong	Part	1	3713 "Light Bluish Gray Technic Bush"					3
13.6	11	Misplacement	Orientation	1	32140 "Black Technic, Liftarm 2 x 4 L-Shape Thick"					3
		Extra	Part	1	32523 "Light Bluish Gray Technic, Liftarm 1 x 3 Thick"					3
13.5	11	Wrong	Part	1	42003 "Light Bluish Gray Technic, Axle and Pin Connector Perpendicular 3L with 2 Pin Holes"					3
13.3	10	Misplacement	Orientation	1	32140 "Black Technic, Liftarm 2 x 4 L-Shape Thick"					3
		Extra	Part	1	32523 "Light Bluish Gray Technic, Liftarm 1 x 3 Thick"					3
Too much differences accumulated.										

Name:	Nathanaël Kulpers	70
Nickname:	Industrial Designer	
Country:	NL / SE	
Submission Date / Time:	2013-11-24 / 17:34	
Submission entry order:	7	
Digital File Type	LDraw / MPD	
Annotations:		

26.4	30	Missing	Part	1	4265c "Light Bluish Gray Technic Bush 1/2 Smooth"					5
26.3	29	Wrong	Part	1	32209 "Dark Bluish Gray Technic, Axle 5.5 with Stop"					3
26.1	28	Wrong	Part	1	87083 "Dark Bluish Gray Technic, Axle 4 with Stop"					3
24.8	27	Misplacement	Orientation	1	60483 "Light Bluish Gray Technic, Liftarm 1 x 2 Thick with Pin Hole and Axle Hole"					3
20.4	18	Missing	Part	1	3713 "Light Bluish Gray Technic Bush"					5
14.4	14	Missing	Part	2	43093 "Blue Technic, Axle Pin with Friction Ridges Lengthwise"					10
14.3		Extra	Part	2	2780 "Black Technic, Pin with Friction Ridges Lengthwise WITH Center Slots"					6
14.2		Wrong	Part	2	32184 "Black Technic, Axle and Pin Connector Perpendicular 3L with Center Pin Hole"					6
13.10	13	Wrong	Color (Visible)	1	6536 "White Technic, Axle and Pin Connector Perpendicular"	LBG	instead of	White		3
13.9	12	Wrong	Part	1	87083 "Dark Bluish Gray Technic, Axle 4 with Stop"					3
13.5	11	Wrong	Part	1	42003 "Light Bluish Gray Technic, Axle and Pin Connector Perpendicular 3L with 2 Pin Holes"					3
6	6	Wrong	Part	1	43093 "Blue Technic, Axle Pin with Friction Ridges Lengthwise"					3
		Missing	Part	1	32054 "Light Bluish Gray Technic, Pin Long with Friction Ridges Lengthwise and Stop Bush"					5
5	5	Extra	Part	1	32140 "Black Technic, Liftarm 2 x 4 L-Shape Thick"					3
		Extra	Part	1	6558 "Blue Technic, Pin Long with Friction Ridges Lengthwise"					3
4		Extra	Part	2	2780 "Black Technic, Pin with Friction Ridges Lengthwise WITH Center Slots"					6

Name:	Jonathan Garcia	77
Nickname:	Timoonn	
Country:	FR	
Submission Date / Time:	2013-11-24 / 17:41	
Submission entry order:	8	
Digital File Type	SR 3D	
Annotations:		

26.4	30	Wrong	Part	1	4265c "Light Bluish Gray Technic Bush 1/2 Smooth"					3
26.3	29	Wrong	Part	1	32209 "Dark Bluish Gray Technic, Axle 5.5 with Stop"					3
26.1	28	Wrong	Part	1	87083 "Dark Bluish Gray Technic, Axle 4 with Stop"					3
24.8	27	Misplacement	Orientation	1	60483 "Light Bluish Gray Technic, Liftarm 1 x 2 Thick with Pin Hole and Axle Hole"					3
24.7	26	Misplacement	Orientation	1	60483 "Light Bluish Gray Technic, Liftarm 1 x 2 Thick with Pin Hole and Axle Hole"					3
20.4	18	Missing	Part	1	3713 "Light Bluish Gray Technic Bush"					5
14.4	14	Missing	Part	2	43093 "Blue Technic, Axle Pin with Friction Ridges Lengthwise"					10
14.3		Extra	Part	2	2780 "Black Technic, Pin with Friction Ridges Lengthwise WITH Center Slots"					6
14.2		Wrong	Part	2	32184 "Black Technic, Axle and Pin Connector Perpendicular 3L with Center Pin Hole"					6
13.10	13	Wrong	Color (Visible)	1	6536 "White Technic, Axle and Pin Connector Perpendicular"	LBG	instead of	White		3
13.9	12	Wrong	Part	1	87083 "Dark Bluish Gray Technic, Axle 4 with Stop"					3
13.5	11	Wrong	Part	1	42003 "Light Bluish Gray Technic, Axle and Pin Connector Perpendicular 3L with 2 Pin Holes"					3
13.4	10	Wrong	Part	1	6558 "Blue Technic, Pin Long with Friction Ridges Lengthwise"					3
7	6	Wrong	Part	1	32140 "Black Technic, Liftarm 2 x 4 L-Shape Thick"					3
		Extra	Part	1	6632 "Black Technic, Liftarm 1 x 3 Thin"					3

Building Instructions Step	Page	Mismatch Type	Mismatch Specific	Occurrences	Color	Part mismatched	Penalties
6		Wrong	Part	1		32054 "Light Bluish Gray Technic, Pin Long with Friction Ridges Lengthwise and Stop Bush"	3
5	1	Missing	Part	1		4519 "Light Bluish Gray Technic, Axle 3"	5
2	3	Extra	Part	2		3713 "Light Bluish Gray Technic Bush"	6
		Wrong	Part	1		32184 "Black Technic, Axle and Pin Connector Perpendicular 3L with Center Pin Hole"	3

Name:		128
Nickname:	Ryan Welsh	
Country:	NL	
Submission Date / Time:	2013-11-24 / 20:08	
Submission entry order:	9	
Digital File Type	LDD	
Annotations:		

28	33	Misplacement	Orientation	3		99012 "Dark Bluish Gray Technic Rotor Blade Small with Axle and Pin Connector End"	9
26.4	30	Missing	Part	1		4265c "Light Bluish Gray Technic Bush 1/2 Smooth"	5
26.3	29	Wrong	Part	1		32209 "Dark Bluish Gray Technic, Axle 5.5 with Stop"	3
26.1	28	Wrong	Part	1		87083 "Dark Bluish Gray Technic, Axle 4 with Stop"	3
24.4	26	Misplacement	Orientation	1		60483 "Black Technic, Liftarm 1 x 2 Thick with Pin Hole and Axle Hole"	3
24.3	25	Extra	Part	1		32062 "Red Technic, Axle 2 Notched"	3
20.4	18	Missing	Part	1		3713 "Light Bluish Gray Technic Bush"	5
20.3		Wrong	Part	1		32209 "Dark Bluish Gray Technic, Axle 5.5 with Stop"	3
18	17	Missing	Part	2		32054 "Light Bluish Gray Technic, Pin Long with Friction Ridges Lengthwise and Stop Bush"	10
14.4	14	Missing	Part	2		43093 "Blue Technic, Axle Pin with Friction Ridges Lengthwise"	10
14.3		Extra	Part	4		2780 "Black Technic, Pin with Friction Ridges Lengthwise WITH Center Slots"	12
14.2		Wrong	Part	2		32184 "Black Technic, Axle and Pin Connector Perpendicular 3L with Center Pin Hole"	6
13.9	12	Missing	Part	1		3713 "Light Bluish Gray Technic Bush"	5
		Wrong	Part	1		87083 "Dark Bluish Gray Technic, Axle 4 with Stop"	3
		Wrong	Part	1		3713 "Light Bluish Gray Technic Bush"	3
		Extra	Part	1		2780 "Black Technic, Pin with Friction Ridges Lengthwise WITH Center Slots"	3
7	6	Misplacement	Deviation	1		32140 "Black Technic, Liftarm 2 x 4 L-Shape Thick"	3
6	6	Missing	Part	1		43093 "Blue Technic, Axle Pin with Friction Ridges Lengthwise"	5
		Missing	Part	1		32054 "Light Bluish Gray Technic, Pin Long with Friction Ridges Lengthwise and Stop Bush"	5
3	4	Misplacement	Orientation	1		32526 "Light Bluish Gray Technic, Liftarm 3 x 5 L-Shape Thick"	3
		Extra	Part	1		60483 "Black Technic, Liftarm 1 x 2 Thick with Pin Hole and Axle Hole"	3
		Extra	Part	1		43093 "Blue Technic, Axle Pin with Friction Ridges Lengthwise"	3
2	3	Missing	Part	1		32184 "Black Technic, Axle and Pin Connector Perpendicular 3L with Center Pin Hole"	5
1	3	Misplacement	Orientation	1		32526 "Light Bluish Gray Technic, Liftarm 3 x 5 L-Shape Thick"	3
		Extra	Part	1		60483 "Black Technic, Liftarm 1 x 2 Thick with Pin Hole and Axle Hole"	3
		Extra	Part	1		43093 "Blue Technic, Axle Pin with Friction Ridges Lengthwise"	3
		Extra	Part	1		6558 "Blue Technic, Pin Long with Friction Ridges Lengthwise"	3
		Extra	Part	1		4519 "Light Bluish Gray Technic, Axle 3"	3

Name:	George Weerts	94
Nickname:	Gworks	
Country:	?	
Submission Date / Time:	2013-11-24 / 21:14	
Submission entry order:	10	
Digital File Type	LDD	
Annotations:		

26.4	30	Missing	Part	1		4265c "Light Bluish Gray Technic Bush 1/2 Smooth"	5
26.3	29	Misplacement	Orientation	1		32209 "Dark Bluish Gray Technic, Axle 5.5 with Stop"	3
24.8	27	Wrong	Part	1		60483 "Light Bluish Gray Technic, Liftarm 1 x 2 Thick with Pin Hole and Axle Hole"	3
24.7	26	Wrong	Part	1		60483 "Light Bluish Gray Technic, Liftarm 1 x 2 Thick with Pin Hole and Axle Hole"	3
20.4	18	Missing	Part	1		3713 "Light Bluish Gray Technic Bush"	5
14.4	14	Missing	Part	2		43093 "Blue Technic, Axle Pin with Friction Ridges Lengthwise"	10
14.3		Extra	Part	2		2780 "Black Technic, Pin with Friction Ridges Lengthwise WITH Center Slots"	6
14.2		Wrong	Part	2		32184 "Black Technic, Axle and Pin Connector Perpendicular 3L with Center Pin Hole"	6
		Extra	Part	1		6558 "Blue Technic, Pin Long with Friction Ridges Lengthwise"	3
13.9	12	Wrong	Part	1		87083 "Dark Bluish Gray Technic, Axle 4 with Stop"	3
13.5	11	Misplacement	Deviation & Orientation	1		42003 "Light Bluish Gray Technic, Axle and Pin Connector Perpendicular 3L with 2 Pin Holes"	3
13.4	10	Missing	Part	1		2780 "Black Technic, Pin with Friction Ridges Lengthwise WITH Center Slots"	5
7	6	Misplacement	Deviation	2		2825 "Light Bluish Gray Technic, Liftarm 1 x 4 Thin with Stud Connector"	6
		Wrong	Part	1		32140 "Black Technic, Liftarm 2 x 4 L-Shape Thick"	3
6	6	Wrong	Part	1		43093 "Blue Technic, Axle Pin with Friction Ridges Lengthwise"	3
		Missing	Part	1		32054 "Light Bluish Gray Technic, Pin Long with Friction Ridges Lengthwise and Stop Bush"	5
4	4	Missing	Part	2		2780 "Black Technic, Pin with Friction Ridges Lengthwise WITH Center Slots"	10
		Extra	Part	2		2780 "Black Technic, Pin with Friction Ridges Lengthwise WITH Center Slots"	6
2	3	Wrong	Part	1		32184 "Black Technic, Axle and Pin Connector Perpendicular 3L with Center Pin Hole"	3
		Extra	Part	1		87082 "Black Technic, Pin Long with Friction Ridges Lengthwise and Center Pin Hole"	3

Name:	Petr Mlčoch	77
Nickname:	Foton	
Country:	CZ	
Submission Date / Time:	2013-11-24 / 21:45	
Submission entry order:	11	
Digital File Type	SR 3D	
Annotations:		

27.1	32	Wrong	Part	1		87082 "Black Technic, Pin Long with Friction Ridges Lengthwise and Center Pin Hole"	3
26.4	30	Wrong	Part	1		4265c "Light Bluish Gray Technic Bush 1/2 Smooth"	3
26.3	29	Wrong	Part	1		32209 "Dark Bluish Gray Technic, Axle 5.5 with Stop"	3
26.1	28	Missing	Part	1		87083 "Dark Bluish Gray Technic, Axle 4 with Stop"	3
24.4	26	Wrong	Part	1		41677 "Blue Technic, Liftarm 1 x 2 Thin"	5
24.3	25	Missing	Part	1		41677 "Blue Technic, Liftarm 1 x 2 Thin"	5
20.4	18	Missing	Part	1		3713 "Light Bluish Gray Technic Bush"	5
20.3		Missing	Part	1		32209 "Dark Bluish Gray Technic, Axle 5.5 with Stop"	5
15	15	Wrong	Part	1		43093 "Blue Technic, Axle Pin with Friction Ridges Lengthwise"	3
		Wrong	Part	1		6632 "Black Technic, Liftarm 1 x 3 Thin"	3
		Missing	Part	1		6632 "Black Technic, Liftarm 1 x 3 Thin"	5
14.4	14	Missing	Part	2		43093 "Blue Technic, Axle Pin with Friction Ridges Lengthwise"	10
14.3		Extra	Part	2		2780 "Black Technic, Pin with Friction Ridges Lengthwise WITH Center Slots"	6
14.2		Wrong	Part	2		32184 "Black Technic, Axle and Pin Connector Perpendicular 3L with Center Pin Hole"	6
		Extra	Part	1		6558 "Blue Technic, Pin Long with Friction Ridges Lengthwise"	3
13.10	13	Wrong	Color (Visible)	1		6536 "White Technic, Axle and Pin Connector Perpendicular"	3
13.9	12	Wrong	Part	1		87083 "Dark Bluish Gray Technic, Axle 4 with Stop"	3
13.5	11	Wrong	Part	1		42003 "Light Bluish Gray Technic, Axle and Pin Connector Perpendicular 3L with 2 Pin Holes"	3

Too much differences accumulated.
Several parts not seen in the file or mysteriously appearing once removing other parts
SR3D crashing often while manipulating this file

Name:	Jernej Krmelj	98
Nickname:	Zblj1987	
Country:	SI	
Submission Date / Time:	2013-11-24 / 22:22	
Submission entry order:	12	
Digital File Type	LDD	
Annotations:		

27.1	32	Missing	Part	1		87082 "Black Technic, Pin Long with Friction Ridges Lengthwise and Center Pin Hole"	5
26.4	30	Missing	Part	1		4265c "Light Bluish Gray Technic Bush 1/2 Smooth"	5
24.8	27	Misplacement	Orientation	1		60483 "Light Bluish Gray Technic, Liftarm 1 x 2 Thick with Pin Hole and Axle Hole"	3
24.7	26	Misplacement	Orientation	1		60483 "Light Bluish Gray Technic, Liftarm 1 x 2 Thick with Pin Hole and Axle Hole"	3
20.4	18	Missing	Part	1		3713 "Light Bluish Gray Technic Bush"	5
14.4	14	Missing	Part	2		43093 "Blue Technic, Axle Pin with Friction Ridges Lengthwise"	10
14.3		Extra	Part	2		2780 "Black Technic, Pin with Friction Ridges Lengthwise WITH Center Slots"	6

Building Instructions Step	Page	Mismatch Type	Mismatch Specific	Occurrences	Color	Part mismatched	Penalties
14.2		Wrong	Part	2		32184 "Black Technic, Axle and Pin Connector Perpendicular 3L with Center Pin Hole"	6
13.6		Missing	Part	1		2780 "Black Technic, Pin with Friction Ridges Lengthwise WITH Center Slots"	3
		Wrong	Part	1		32140 "Black Technic, Liftarm 2 x 4 L-Shape Thick"	3
		Extra	Part	1		60483 "Light Bluish Gray Technic, Liftarm 1 x 2 Thick with Pin Hole and Axle Hole"	3
13.5	11	Wrong	Part	1		42003 "Light Bluish Gray Technic, Axle and Pin Connector Perpendicular 3L with 2 Pin Holes"	3
13.4	10	Missing	Part	1		2780 "Black Technic, Pin with Friction Ridges Lengthwise WITH Center Slots"	3
		Wrong	Part	1		32140 "Black Technic, Liftarm 2 x 4 L-Shape Thick"	3
		Extra	Part	1		60483 "Light Bluish Gray Technic, Liftarm 1 x 2 Thick with Pin Hole and Axle Hole"	3
7	6	Wrong	Part	2		2825 "Light Bluish Gray Technic, Liftarm 1 x 4 Thin with Stud Connector"	6
		Wrong	Part	1		32140 "Black Technic, Liftarm 2 x 4 L-Shape Thick"	3
		Extra	Part	1		32062 "Red Technic, Axle 2 Notched"	3
		Extra	Part	1		60483 "Black Gray Technic, Liftarm 1 x 2 Thick with Pin Hole and Axle Hole"	3
6	6	Missing	Part	1		43093 "Blue Technic, Axle Pin with Friction Ridges Lengthwise"	5
		Missing	Part	1		32054 "Light Bluish Gray Technic, Pin Long with Friction Ridges Lengthwise and Stop Bush"	5
4	4	Extra	Part	2		2780 "Black Technic, Pin with Friction Ridges Lengthwise WITH Center Slots"	6
2	3	Wrong	Part	1		32184 "Black Technic, Axle and Pin Connector Perpendicular 3L with Center Pin Hole"	3

Name:	Andrew Hagber	110
Nickname:	Saberwing40k	
Country:	US	
Submission Date / Time:	2013-11-25 / 04:44	
Submission entry order:	13	
Digital File Type	LDD	
Annotations:		

28	33	Misplacement	Orientation	3		99012 "Dark Bluish Gray Technic Rotor Blade Small with Axle and Pin Connector End"	9
27.1	32	Missing	Part	1		87082 "Black Technic, Pin Long with Friction Ridges Lengthwise and Center Pin Hole"	5
26.4	30	Missing	Part	1		4265c "Light Bluish Gray Technic Bush 1/2 Smooth"	5
26.3	29	Wrong	Part	1		32209 "Dark Bluish Gray Technic, Axle 5.5 with Stop"	3
24.8	27	Wrong	Part	1		60483 "Light Bluish Gray Technic, Liftarm 1 x 2 Thick with Pin Hole and Axle Hole"	3
		Extra	Part	1		41677 "Light Bluish Gray Technic, Liftarm 1 x 2 Thin"	3
24.7	26	Wrong	Part	1		60483 "Light Bluish Gray Technic, Liftarm 1 x 2 Thick with Pin Hole and Axle Hole"	3
		Extra	Part	1		41677 "Light Bluish Gray Technic, Liftarm 1 x 2 Thin"	3
20.4	18	Missing	Part	1		3713 "Light Bluish Gray Technic Bush"	5
18	17	Extra	Part	1		32316 "Light Bluish Gray Technic, Liftarm 1 x 5 Thick"	3
		Wrong	Part	2		32054 "Light Bluish Gray Technic, Pin Long with Friction Ridges Lengthwise and Stop Bush"	6
14.3	14	Extra	Part	2		2780 "Black Technic, Pin with Friction Ridges Lengthwise WITH Center Slots"	6
14.2		Wrong	Part	2		32184 "Black Technic, Axle and Pin Connector Perpendicular 3L with Center Pin Hole"	6
		Extra	Part	2		6632 "Black Technic, Liftarm 1 x 3 Thin"	6
13.10	13	Wrong	Color (Visible)	1	LBG	instead of White	3
13.9	12	Wrong	Part	1		87083 "Dark Bluish Gray Technic, Axle 4 with Stop"	3
		Missing	Part	1		3713 "Light Bluish Gray Technic Bush"	5
13.5	11	Wrong	Part	1		42003 "Light Bluish Gray Technic, Axle and Pin Connector Perpendicular 3L with 2 Pin Holes"	3
13.4	10	Wrong	Part	1		6558 "Blue Technic, Pin Long with Friction Ridges Lengthwise"	3
7	6	Wrong	Part	2		2825 "Light Bluish Gray Technic, Liftarm 1 x 4 Thin with Stud Connector"	6
		Misplacement	Deviation	1		32140 "Black Technic, Liftarm 2 x 4 L-Shape Thick"	3
		Extra	Part	1		32062 "Red Technic, Axle 2 Notched"	3
		Extra	Part	2		6536 "White Technic, Axle and Pin Connector Perpendicular"	6
		Extra	Part	2		43093 "Blue Technic, Axle Pin with Friction Ridges Lengthwise"	6
		Extra	Part	1		6558 "Blue Technic, Pin Long with Friction Ridges Lengthwise"	3
						Too much differences accumulated.	

Name:	Stephan den Ridder	110
Nickname:	Stephan3321	
Country:	NL	
Submission Date / Time:	2013-11-25 / 16:02	
Submission entry order:	14	
Digital File Type	LDD	
Annotations:		

28	33	Misplacement	Orientation	3		99012 "Dark Bluish Gray Technic Rotor Blade Small with Axle and Pin Connector End"	9
27.1	32	Missing	Part	1		87082 "Black Technic, Pin Long with Friction Ridges Lengthwise and Center Pin Hole"	5
26.4	30	Missing	Part	1		4265c "Light Bluish Gray Technic Bush 1/2 Smooth"	5
26.3	29	Wrong	Part	1		32209 "Dark Bluish Gray Technic, Axle 5.5 with Stop"	3
23.2	24	Missing	Part	1		4265c "Light Bluish Gray Technic Bush 1/2 Smooth"	5
23.1		Missing	Part	1		43093 "Blue Technic, Axle Pin with Friction Ridges Lengthwise"	5
22.5	23	Missing	Part	1		4265c "Light Bluish Gray Technic Bush 1/2 Smooth"	5
22.3	22	Missing	Part	1		43093 "Blue Technic, Axle Pin with Friction Ridges Lengthwise"	5
20.5	19	Missing	Part	1		43093 "Blue Technic, Axle Pin with Friction Ridges Lengthwise"	5
18	17	Wrong	Part	2		32054 "Light Bluish Gray Technic, Pin Long with Friction Ridges Lengthwise and Stop Bush"	6
		Extra	Part	2		43093 "Blue Technic, Axle Pin with Friction Ridges Lengthwise"	6
15	15	Missing	Part	1		6632 "Black Technic, Liftarm 1 x 3 Thin"	5
14.4	14	Missing	Part	2		43093 "Blue Technic, Axle Pin with Friction Ridges Lengthwise"	10
14.3		Extra	Part	2		2780 "Black Technic, Pin with Friction Ridges Lengthwise WITH Center Slots"	6
14.2		Missing	Part	2		32184 "Black Technic, Axle and Pin Connector Perpendicular 3L with Center Pin Hole"	10
13.9	12	Wrong	Part	1		3713 "Light Bluish Gray Technic Bush"	3
		Wrong	Part	1		87083 "Dark Bluish Gray Technic, Axle 4 with Stop"	3
13.5	11	Wrong	Part	1		32523 "Blue Technic, Liftarm 1 x 3 Thick"	3
		Wrong	Part	1		42003 "Light Bluish Gray Technic, Axle and Pin Connector Perpendicular 3L with 2 Pin Holes"	3
13.4	10	Wrong	Part	1		6558 "Blue Technic, Pin Long with Friction Ridges Lengthwise"	3
13.1	9	Missing	Part	1		6632 "Black Technic, Liftarm 1 x 3 Thin"	5
						Too much differences accumulated.	

Name:	Robert Schneiduch	97
Nickname:	ROSch	
Country:	RO	
Submission Date / Time:	2013-11-25 / 20:26	
Submission entry order:	15	
Digital File Type	LDD	
Annotations:		

27.1	32	Missing	Part	1		87082 "Black Technic, Pin Long with Friction Ridges Lengthwise and Center Pin Hole"	5
26.4	30	Missing	Part	1		4265c "Light Bluish Gray Technic Bush 1/2 Smooth"	5
26.3	29	Wrong	Part	1		32209 "Dark Bluish Gray Technic, Axle 5.5 with Stop"	3
24.8	27	Misplacement	Orientation	1		60483 "Light Bluish Gray Technic, Liftarm 1 x 2 Thick with Pin Hole and Axle Hole"	3
24.7	26	Misplacement	Orientation	1		60483 "Light Bluish Gray Technic, Liftarm 1 x 2 Thick with Pin Hole and Axle Hole"	3
20.4	18	Misplacement	Deviation	1		3713 "Light Bluish Gray Technic Bush"	3
20.3		Wrong	Part	1		32209 "Dark Bluish Gray Technic, Axle 5.5 with Stop"	3
18	17	Wrong	Part	2		32054 "Light Bluish Gray Technic, Pin Long with Friction Ridges Lengthwise and Stop Bush"	6
14.4	14	Wrong	Part	1		43093 "Blue Technic, Axle Pin with Friction Ridges Lengthwise"	3
14.3		Extra	Part	2		2780 "Black Technic, Pin with Friction Ridges Lengthwise WITH Center Slots"	6
14.2		Wrong	Part	2		32184 "Black Technic, Axle and Pin Connector Perpendicular 3L with Center Pin Hole"	6
13.10	13	Wrong	Color (Visible)	1	LBG	instead of White	3
13.9	12	Wrong	Part	1		3713 "Light Bluish Gray Technic Bush"	3
		Missing	Part	1		87083 "Dark Bluish Gray Technic, Axle 4 with Stop"	5
		Extra	Part	1		43093 "Blue Technic, Axle Pin with Friction Ridges Lengthwise"	3
13.4	10	Wrong	Part	1		6558 "Blue Technic, Pin Long with Friction Ridges Lengthwise"	3
7	6	Misplacement	Deviation	1		32140 "Black Technic, Liftarm 2 x 4 L-Shape Thick"	3
		Extra	Part	1		32062 "Red Technic, Axle 2 Notched"	3
		Extra	Part	1		4519 "Light Bluish Gray Technic, Axle 3"	3
6	6	Missing	Part	1		43093 "Blue Technic, Axle Pin with Friction Ridges Lengthwise"	5
		Missing	Part	1		32054 "Light Bluish Gray Technic, Pin Long with Friction Ridges Lengthwise and Stop Bush"	5
5	5	Extra	Part	1		32140 "Black Technic, Liftarm 2 x 4 L-Shape Thick"	3
		Extra	Part	1		6558 "Blue Technic, Pin Long with Friction Ridges Lengthwise"	3
		Wrong	Part	1		4519 "Light Bluish Gray Technic, Axle 3"	3
2	3	Wrong	Part	1		32184 "Black Technic, Axle and Pin Connector Perpendicular 3L with Center Pin Hole"	3

Building Instructions Step	Page	Mismatch Type	Mismatch Specific	Occurrences	Color	Part mismatched	Penalties
----------------------------	------	---------------	-------------------	-------------	-------	-----------------	-----------

Name:	Algirdas Lašas	105
Nickname:	Lashas	
Country:	LT	
Submission Date / Time:	2013-11-25 / 22:58	
Submission entry order:	16	
Digital File Type	LDD	
Annotations:		

28	33	Misplacement	Orientation	3		99012 "Dark Bluish Gray Technic Rotor Blade Small with Axle and Pin Connector End"	9
26.4	30	Missing	Part	1		4265c "Light Bluish Gray Technic Bush 1/2 Smooth"	5
26.3	29	Wrong	Part	1		32209 "Dark Bluish Gray Technic, Axle 5.5 with Stop"	3
26.1	28	Wrong	Part	1		87083 "Dark Bluish Gray Technic, Axle 4 with Stop"	3
23.2	24	Wrong	Color (Visible)	1		4265c "Light Bluish Gray Technic Bush 1/2 Smooth"	3
22.5	23	Wrong	Color (Invisible)	1		4265c "Light Bluish Gray Technic Bush 1/2 Smooth"	2
14.4	14	Missing	Part	2		43093 "Blue Technic, Axle Pin with Friction Ridges Lengthwise"	10
14.3		Extra	Part	2		2780 "Black Technic, Pin with Friction Ridges Lengthwise WITH Center Slots"	6
14.2		Wrong	Part	2		32184 "Black Technic, Axle and Pin Connector Perpendicular 3L with Center Pin Hole"	6
		Extra	Part	2		4265c "Black Technic Bush 1/2 Smooth"	6
13.10	13	Wrong	Color (Visible)	1		6536 "White Technic, Axle and Pin Connector Perpendicular"	3
13.9	12	Wrong	Part	1	LBG	instead of White	3
13.5	11	Wrong	Part	1		87083 "Dark Bluish Gray Technic, Axle 4 with Stop"	3
7	6	Misplacement	Deviation	1		42003 "Light Bluish Gray Technic, Axle and Pin Connector Perpendicular 3L with 2 Pin Holes"	3
		Extra	Part	1		32140 "Black Technic, Liftarm 2 x 4 L-Shape Thick"	3
		Extra	Part	2		4519 "Light Bluish Gray Technic, Axle 3"	3
		Extra	Part	2		6536 "Black Technic, Axle and Pin Connector Perpendicular"	6
		Extra	Part	2		43093 "Blue Technic, Axle Pin with Friction Ridges Lengthwise"	6
		Extra	Part	1		6558 "Blue Technic, Pin Long with Friction Ridges Lengthwise"	3
6	6	Missing	Part	1		43093 "Blue Technic, Axle Pin with Friction Ridges Lengthwise"	5
		Missing	Part	1		32054 "Light Bluish Gray Technic, Pin Long with Friction Ridges Lengthwise and Stop Bush"	5
5	5	Extra	Part	1		32140 "Black Technic, Liftarm 2 x 4 L-Shape Thick"	3
		Extra	Part	1		32062 "Red Technic, Axle 2 Notched"	3
4	4	Extra	Part	2		2780 "Black Technic, Pin with Friction Ridges Lengthwise WITH Center Slots"	6

Name:	Jeremy Streatfield	71
Nickname:		
Country:	AU	
Submission Date / Time:	2013-11-26 / 02:22	
Submission entry order:	17	
Digital File Type	LDraw	
Annotations:		

26.4	30	Missing	Part	1		4265c "Light Bluish Gray Technic Bush 1/2 Smooth"	5
26.1	28	Wrong	Part	1		87083 "Dark Bluish Gray Technic, Axle 4 with Stop"	3
14.4	14	Missing	Part	2		43093 "Blue Technic, Axle Pin with Friction Ridges Lengthwise"	10
14.3		Extra	Part	2		2780 "Black Technic, Pin with Friction Ridges Lengthwise WITH Center Slots"	6
14.2		Missing	Part	2		32184 "Black Technic, Axle and Pin Connector Perpendicular 3L with Center Pin Hole"	10
13.10	13	Wrong	Color (Visible)	1		6536 "White Technic, Axle and Pin Connector Perpendicular"	3
13.5	11	Wrong	Part	1	LBG	instead of White	3
		Wrong	Part	1		42003 "Light Bluish Gray Technic, Axle and Pin Connector Perpendicular 3L with 2 Pin Holes"	3
		Wrong	Part	1		32523 "Blue Technic, Liftarm 1 x 3 Thick"	3
13.4	10	Wrong	Part	1		6558 "Blue Technic, Pin Long with Friction Ridges Lengthwise"	3
7.1	6	Wrong	Part	1		32140 "Black Technic, Liftarm 2 x 4 L-Shape Thick"	3
		Extra	Part	1		32017 "Black Technic, Liftarm 1 x 5 Thin"	3
6	6	Wrong	Part	1		43093 "Blue Technic, Axle Pin with Friction Ridges Lengthwise"	3
		Missing	Part	1		32054 "Light Bluish Gray Technic, Pin Long with Friction Ridges Lengthwise and Stop Bush"	5
4	4	Extra	Part	2		2780 "Black Technic, Pin with Friction Ridges Lengthwise WITH Center Slots"	6
2	3	Missing	Part	1		32184 "Black Technic, Axle and Pin Connector Perpendicular 3L with Center Pin Hole"	5

Name:	Michael Kamas	82
Nickname:	CARreverseEngineering	
Country:	US	
Submission Date / Time:	2013-11-26 / 05:39	
Submission entry order:	18	
Digital File Type	LDD	
Annotations:		

26.4	30	Missing	Part	1		4265c "Light Bluish Gray Technic Bush 1/2 Smooth"	5
26.3	29	Wrong	Part	1		32209 "Dark Bluish Gray Technic, Axle 5.5 with Stop"	3
23.2	24	Wrong	Part	1		4265c "Light Bluish Gray Technic Bush 1/2 Smooth"	3
22.5	23	Wrong	Part	1		4265c "Light Bluish Gray Technic Bush 1/2 Smooth"	3
14.4	14	Wrong	Part	2		43093 "Blue Technic, Axle Pin with Friction Ridges Lengthwise"	6
14.3		Extra	Part	2		2780 "Black Technic, Pin with Friction Ridges Lengthwise WITH Center Slots"	6
14.2		Missing	Part	2		32184 "Black Technic, Axle and Pin Connector Perpendicular 3L with Center Pin Hole"	10
13.9	12	Wrong	Part	2		3713 "Light Bluish Gray Technic Bush"	3
		Misplacement	Deviation	1		87083 "Dark Bluish Gray Technic, Axle 4 with Stop"	3
13.5	11	Wrong	Part	1		42003 "Light Bluish Gray Technic, Axle and Pin Connector Perpendicular 3L with 2 Pin Holes"	3
		Extra	Part	1		32062 "Red Technic, Axle 2 Notched"	3
		Extra	Part	1		60483 "Black Technic, Liftarm 1 x 2 Thick with Pin Hole and Axle Hole"	3
13.4	10	Missing	Part	1		2780 "Black Technic, Pin with Friction Ridges Lengthwise WITH Center Slots"	3
7.1	6	Wrong	Part	1		32140 "Black Technic, Liftarm 2 x 4 L-Shape Thick"	3
		Extra	Part	1		6632 "Black Technic, Liftarm 1 x 3 Thin"	3
6	6	Misplacement	Deviation	1		43093 "Blue Technic, Axle Pin with Friction Ridges Lengthwise"	3
		Missing	Part	1		32054 "Light Bluish Gray Technic, Pin Long with Friction Ridges Lengthwise and Stop Bush"	5
4	4	Misplacement	Deviation	2		6558 "Blue Technic, Pin Long with Friction Ridges Lengthwise"	6
		Wrong	Color (Invisible)	1		6536 "White Technic, Axle and Pin Connector Perpendicular"	2
2	3	Wrong	Part	1		32184 "Black Technic, Axle and Pin Connector Perpendicular 3L with Center Pin Hole"	3
		Extra	Part	1		60483 "Light Bluish Gray Technic, Liftarm 1 x 2 Thick with Pin Hole and Axle Hole"	3

Name:	Philippe Hurbain	67
Nickname:	Philo	
Country:	FR	
Submission Date / Time:	2013-11-26 / 15:24	
Submission entry order:	19	
Digital File Type	SR 3D	
Annotations:		

26.4	30	Missing	Part	1		4265c "Light Bluish Gray Technic Bush 1/2 Smooth"	5
26.3	29	Wrong	Part	1		32209 "Dark Bluish Gray Technic, Axle 5.5 with Stop"	3
23.2	24	Wrong	Color (Visible)	1		4265c "Light Bluish Gray Technic Bush 1/2 Smooth"	3
22.5	23	Wrong	Color (Invisible)	1		4265c "Light Bluish Gray Technic Bush 1/2 Smooth"	2
20.4	18	Missing	Part	1		3713 "Light Bluish Gray Technic Bush"	5
20.1		Wrong	Part	1		3705 "Black Technic, Axle 4"	3
14.4	14	Missing	Part	2		43093 "Blue Technic, Axle Pin with Friction Ridges Lengthwise"	10
14.3		Extra	Part	2		2780 "Black Technic, Pin with Friction Ridges Lengthwise WITH Center Slots"	6
14.2		Wrong	Part	2		32184 "Black Technic, Axle and Pin Connector Perpendicular 3L with Center Pin Hole"	6
13.10	13	Wrong	Color (Visible)	1		6536 "White Technic, Axle and Pin Connector Perpendicular"	3
13.9	12	Wrong	Part	1	LBG	instead of White	3
13.5	11	Wrong	Part	1		87083 "Dark Bluish Gray Technic, Axle 4 with Stop"	3
11	8	Extra	Part	1		42003 "Light Bluish Gray Technic, Axle and Pin Connector Perpendicular 3L with 2 Pin Holes"	3
		Extra	Part	1		32140 "Black Technic, Liftarm 2 x 4 L-Shape Thick"	3
		Extra	Part	1		6558 "Blue Technic, Pin Long with Friction Ridges Lengthwise"	3
7.2	6	Wrong	Part	2		2825 "Light Bluish Gray Technic, Liftarm 1 x 4 Thin with Stud Connector"	6
7.1	6	Extra	Part	1		32062 "Red Technic, Axle 2 Notched"	3

Name:	Alex Marik	83
Nickname:		

Building Instructions Step										Penalties
Page	Mismatch Type	Mismatch Specific	Occurrences	Color	Part mismatched					
Country: BR										
Submission Date / Time: 2013-11-26 / 20:35										
Submission entry order: 20										
Digital File Type: LDD										
Annotations:										
26.4	30	Missing	Part	1	4265c "Light Bluish Gray Technic Bush 1/2 Smooth"					5
26.3	29	Wrong	Part	1	32209 "Dark Bluish Gray Technic, Axle 5.5 with Stop"					3
26.1	28	Wrong	Part	1	87083 "Dark Bluish Gray Technic, Axle 4 with Stop"					3
24.8	27	Misplacement	Orientation	1	60483 "Light Bluish Gray Technic, Liftarm 1 x 2 Thick with Pin Hole and Axle Hole"					3
24.7	26	Misplacement	Orientation	1	60483 "Light Bluish Gray Technic, Liftarm 1 x 2 Thick with Pin Hole and Axle Hole"					3
20.4	18	Wrong	Part	1	3713 "Light Bluish Gray Technic Bush"					3
20.3		Wrong	Part	1	32209 "Dark Bluish Gray Technic, Axle 5.5 with Stop"					3
15	15	Wrong	Part	1	43093 "Blue Technic, Axle Pin with Friction Ridges Lengthwise"					3
		Wrong	Part	1	6632 "Black Technic, Liftarm 1 x 3 Thin"					3
		Missing	Part	1	6632 "Black Technic, Liftarm 1 x 3 Thin"					5
14.4	14	Missing	Part	2	43093 "Blue Technic, Axle Pin with Friction Ridges Lengthwise"					10
14.3		Extra	Part	2	2780 "Black Technic, Pin with Friction Ridges Lengthwise WITH Center Slots"					6
14.2		Wrong	Part	2	32184 "Black Technic, Axle and Pin Connector Perpendicular 3L with Center Pin Hole"					6
14.1		Wrong	Part	1	42003 "Light Bluish Gray Technic, Axle and Pin Connector Perpendicular 3L with 2 Pin Holes"					3
		Wrong	Part	1	32073 "Light Bluish Gray Technic, Axle 5"					3
		Extra	Part	6	Several					18
13.10	13	Wrong	Color (Visible)	1	6536 "White Technic, Axle and Pin Connector Perpendicular"	LBG	instead of	White		3
Too much differences to proceed counting mismatches from this point.										
Name: Tomáš Vít										61
Nickname: X-Sonic										
Country: CZ										
Submission Date / Time: 2013-11-26 / 23:08										
Submission entry order: 21										
Digital File Type: LDD										
Annotations: Not the exact color used for all Tan elements (kind of systematic error or unawareness)										
28	33	Misplacement	Orientation	3	99012 "Dark Bluish Gray Technic Rotor Blade Small with Axle and Pin Connector End"					9
26.4	30	Wrong	Part	1	4265c "Light Bluish Gray Technic Bush 1/2 Smooth"					3
26.3	29	Wrong	Part	1	32209 "Dark Bluish Gray Technic, Axle 5.5 with Stop"					3
20.4	18	Missing	Part	1	3713 "Light Bluish Gray Technic Bush"					5
14.2	14	Wrong	Part	2	32184 "Black Technic, Axle and Pin Connector Perpendicular 3L with Center Pin Hole"					6
		Extra	Part	2	6632 "Black Technic, Liftarm 1 x 3 Thin"					6
13.10	13	Wrong	Color (Visible)	1	6536 "White Technic, Axle and Pin Connector Perpendicular"	LBG	instead of	White		3
13.5	11	Wrong	Part	1	42003 "Light Bluish Gray Technic, Axle and Pin Connector Perpendicular 3L with 2 Pin Holes"					3
7	6	Wrong	Part	2	2825 "Light Bluish Gray Technic, Liftarm 1 x 4 Thin with Stud Connector"					6
		Extra	Part	1	32062 "Red Technic, Axle 2 Notched"					3
6	6	Misplacement	Deviation	1	43093 "Blue Technic, Axle Pin with Friction Ridges Lengthwise"					3
		Missing	Part	1	32054 "Light Bluish Gray Technic, Pin Long with Friction Ridges Lengthwise and Stop Bush"					5
1	3	Wrong	Part	1	32526 "Light Bluish Gray Technic, Liftarm 3 x 5 L-Shape Thick"					3
		Extra	Part	1	32140 "Black Technic, Liftarm 2 x 4 L-Shape Thick"					3
Name: Michael Redepenning										71
Nickname: bachaddict										
Country: NZ										
Submission Date / Time: 2013-11-27 / 05:33										
Submission entry order: 22										
Digital File Type: LDD										
Annotations:										
28	33	Misplacement	Orientation	3	99012 "Dark Bluish Gray Technic Rotor Blade Small with Axle and Pin Connector End"					9
26.4	30	Missing	Part	1	4265c "Light Bluish Gray Technic Bush 1/2 Smooth"					5
26.3	29	Wrong	Part	1	32209 "Dark Bluish Gray Technic, Axle 5.5 with Stop"					3
24.8	27	Misplacement	Orientation	1	60483 "Light Bluish Gray Technic, Liftarm 1 x 2 Thick with Pin Hole and Axle Hole"					3
24.7	26	Misplacement	Orientation	1	60483 "Light Bluish Gray Technic, Liftarm 1 x 2 Thick with Pin Hole and Axle Hole"					3
22.4	22	Wrong	Color (Visible)	1	6538c "Light Bluish Gray Technic, Axle Connector (Smooth with x Hole + Orientation)"	DBG	instead of	LBG		3
14.4	14	Missing	Part	2	43093 "Blue Technic, Axle Pin with Friction Ridges Lengthwise"					10
14.3		Extra	Part	2	2780 "Black Technic, Pin with Friction Ridges Lengthwise WITH Center Slots"					6
14.2		Wrong	Part	2	32184 "Black Technic, Axle and Pin Connector Perpendicular 3L with Center Pin Hole"					6
13.10	13	Wrong	Color (Visible)	1	6536 "White Technic, Axle and Pin Connector Perpendicular"	LBG	instead of	White		3
13.9	12	Wrong	Part	1	87083 "Dark Bluish Gray Technic, Axle 4 with Stop"					3
13.4	10	Wrong	Part	1	6558 "Blue Technic, Pin Long with Friction Ridges Lengthwise"					3
7	6	Wrong	Part	2	2825 "Light Bluish Gray Technic, Liftarm 1 x 4 Thin with Stud Connector"					6
6	6	Wrong	Part	1	43093 "Blue Technic, Axle Pin with Friction Ridges Lengthwise"					3
		Missing	Part	1	32054 "Light Bluish Gray Technic, Pin Long with Friction Ridges Lengthwise and Stop Bush"					5
Name: zukkee										67
Nickname: KR										
Country: KR										
Submission Date / Time: 2013-11-27 / 10:04										
Submission entry order: 23										
Digital File Type: LDD										
Annotations:										
28	33	Misplacement	Orientation	3	99012 "Dark Bluish Gray Technic Rotor Blade Small with Axle and Pin Connector End"					9
27.3		Missing	Part	1	32184 "Black Technic, Axle and Pin Connector Perpendicular 3L with Center Pin Hole"					5
		Missing	Part	2	43093 "Blue Technic, Axle Pin with Friction Ridges Lengthwise"					10
		Missing	Part	1	32002 "Tan Technic, Pin 3/4"					5
27.1	32	Missing	Part	1	87082 "Black Technic, Pin Long with Friction Ridges Lengthwise and Center Pin Hole"					5
26.4	30	Wrong	Part	1	4265c "Light Bluish Gray Technic Bush 1/2 Smooth"					3
26.3	29	Wrong	Part	1	32209 "Dark Bluish Gray Technic, Axle 5.5 with Stop"					3
26.1	28	Wrong	Part	1	87083 "Dark Bluish Gray Technic, Axle 4 with Stop"					3
24.8	27	Wrong	Part	1	60483 "Light Bluish Gray Technic, Liftarm 1 x 2 Thick with Pin Hole and Axle Hole"					3
24.7	26	Wrong	Part	1	60483 "Light Bluish Gray Technic, Liftarm 1 x 2 Thick with Pin Hole and Axle Hole"					3
24.5		Wrong	Part	1	6632 "Black Technic, Liftarm 1 x 3 Thin"					3
24.4		Wrong	Part	1	60483 "Black Technic, Liftarm 1 x 2 Thick with Pin Hole and Axle Hole"					3
24.3	25	Wrong	Part	1	32062 "Red Technic, Axle 2 Notched"					3
		Extra	Part	1	32002 "Dark Bluish Gray Technic, Pin 3/4"					3
24.2		Wrong	Part	1	6632 "Black Technic, Liftarm 1 x 3 Thin"					3
23.2	24	Wrong	Part	1	4265c "Light Bluish Gray Technic Bush 1/2 Smooth"					3
Too much differences seen ahead										
Name: Jan Guerquin										79
Nickname: rotor										
Country: ?										
Submission Date / Time: 2013-11-27 / 12:45										
Submission entry order: 24										
Digital File Type: LDraw										
Annotations:										
28	33	Misplacement	Orientation	3	99012 "Dark Bluish Gray Technic Rotor Blade Small with Axle and Pin Connector End"					9
27.1	32	Missing	Part	1	87082 "Black Technic, Pin Long with Friction Ridges Lengthwise and Center Pin Hole"					5
26.4	30	Missing	Part	1	4265c "Light Bluish Gray Technic Bush 1/2 Smooth"					5
26.1	28	Wrong	Part	1	87083 "Dark Bluish Gray Technic, Axle 4 with Stop"					3
20.4	18	Missing	Part	1	3713 "Light Bluish Gray Technic Bush"					5
14.4	14	Missing	Part	2	43093 "Blue Technic, Axle Pin with Friction Ridges Lengthwise"					10
14.2		Missing	Part	2	32184 "Black Technic, Axle and Pin Connector Perpendicular 3L with Center Pin Hole"					10
13.10	13	Wrong	Color (Visible)	1	6536 "White Technic, Axle and Pin Connector Perpendicular"	LBG	instead of	White		3
13.9	12	Wrong	Part	1	87083 "Dark Bluish Gray Technic, Axle 4 with Stop"					3

Building Instructions Step	Page	Mismatch Type	Mismatch Specific	Occurrences	Color	Part mismatched	Penalties
13.5	11	Wrong	Part	1		42003 "Light Bluish Gray Technic, Axle and Pin Connector Perpendicular 3L with 2 Pin Holes"	3
7.2	6	Wrong	Part	2		2825 "Light Bluish Gray Technic, Liftarm 1 x 4 Thin with Stud Connector"	6
7.1		Extra	Part	1		32062 "Red Technic, Axle 2 Notched"	3
6	6	Wrong	Part	1		43093 "Blue Technic, Axle Pin with Friction Ridges Lengthwise"	3
		Missing	Part	1		32054 "Light Bluish Gray Technic, Pin Long with Friction Ridges Lengthwise and Stop Bush"	5
2	3	Wrong	Part	1		32184 "Black Technic, Axle and Pin Connector Perpendicular 3L with Center Pin Hole"	3
		Extra	Part	1		32140 "Black Technic, Liftarm 2 x 4 L-Shape Thick"	3

Name:	Christophe Siquet	113
Nickname:	csiquet	
Country:	PT	
Submission Date / Time:	2013-11-27 / 14:09	
Submission entry order:	25	
Digital File Type	LDD	
Annotations:		

28	33	Misplacement	Orientation	3		99012 "Dark Bluish Gray Technic Rotor Blade Small with Axle and Pin Connector End"	9
27.1	32	Missing	Part	1		87082 "Black Technic, Pin Long with Friction Ridges Lengthwise and Center Pin Hole"	5
26.4	30	Missing	Part	1		4265c "Light Bluish Gray Technic Bush 1/2 Smooth"	5
26.3	29	Wrong	Part	1		32209 "Dark Bluish Gray Technic, Axle 5.5 with Stop"	3
26.1	28	Wrong	Part	1		87083 "Dark Bluish Gray Technic, Axle 4 with Stop"	3
24.8	27	Misplacement	Orientation	1		60483 "Light Bluish Gray Technic, Liftarm 1 x 2 Thick with Pin Hole and Axle Hole"	3
24.7	26	Misplacement	Orientation	1		60483 "Light Bluish Gray Technic, Liftarm 1 x 2 Thick with Pin Hole and Axle Hole"	3
24.4		Wrong	Part	1		60483 "Black Technic, Liftarm 1 x 2 Thick with Pin Hole and Axle Hole"	3
		Wrong	Part	1		41677 "Blue Technic, Liftarm 1 x 2 Thin"	3
		Missing	Part	1		41677 "Blue Technic, Liftarm 1 x 2 Thin"	5
15	15	Wrong	Part	1		43093 "Blue Technic, Axle Pin with Friction Ridges Lengthwise"	3
		Wrong	Part	1		6632 "Black Technic, Liftarm 1 x 3 Thin"	3
		Missing	Part	1		6632 "Black Technic, Liftarm 1 x 3 Thin"	5
14.4	14	Missing	Part	2		43093 "Blue Technic, Axle Pin with Friction Ridges Lengthwise"	10
14.3		Extra	Part	2		2780 "Black Technic, Pin with Friction Ridges Lengthwise WITH Center Slots"	6
14.2		Wrong	Part	2		32184 "Black Technic, Axle and Pin Connector Perpendicular 3L with Center Pin Hole"	6
13.10	13	Wrong	Color (Visible)	1		6536 "White Technic, Axle and Pin Connector Perpendicular"	3
13.9	12	Wrong	Part	1		87083 "Dark Bluish Gray Technic, Axle 4 with Stop"	3
13.5	11	Wrong	Part	1		42003 "Light Bluish Gray Technic, Axle and Pin Connector Perpendicular 3L with 2 Pin Holes"	3
		Wrong	Part	1		32523 "Blue Technic, Liftarm 1 x 3 Thick"	3
13.4	10	Wrong	Part	1		6558 "Blue Technic, Pin Long with Friction Ridges Lengthwise"	3
13.1	9	Wrong	Part	1		43093 "Blue Technic, Axle Pin with Friction Ridges Lengthwise"	3
		Wrong	Part	1		6632 "Black Technic, Liftarm 1 x 3 Thin"	3
		Missing	Part	1		6632 "Black Technic, Liftarm 1 x 3 Thin"	5
7	6	Wrong	Part	2		2825 "Light Bluish Gray Technic, Liftarm 1 x 4 Thin with Stud Connector"	6
		Extra	Part	1		32062 "Red Technic, Axle 2 Notched"	3
		Misplacement	Deviation	1		32140 "Black Technic, Liftarm 2 x 4 L-Shape Thick"	3
						Too much differences accumulated.	

Name:	Eric Albrecht	87
Nickname:	Blakbird	
Country:	US	
Submission Date / Time:	2013-11-27 / 21:34	
Submission entry order:	26	
Digital File Type	LDraw	
Annotations:		

28	33	Misplacement	Orientation	3		99012 "Dark Bluish Gray Technic Rotor Blade Small with Axle and Pin Connector End"	9
27.1	32	Wrong	Part	1		87082 "Black Technic, Pin Long with Friction Ridges Lengthwise and Center Pin Hole"	5
26.4	30	Missing	Part	1		4265c "Light Bluish Gray Technic Bush 1/2 Smooth"	5
26.3	29	Wrong	Part	1		32209 "Dark Bluish Gray Technic, Axle 5.5 with Stop"	3
26.1	28	Wrong	Part	1		87083 "Dark Bluish Gray Technic, Axle 4 with Stop"	3
24.3	25	Extra	Part	1		32062 "Red Technic, Axle 2 Notched"	3
20.4	18	Wrong	Part	1		3713 "Light Bluish Gray Technic Bush"	3
20.3		Wrong	Part	1		32209 "Dark Bluish Gray Technic, Axle 5.5 with Stop"	3
18	17	Wrong	Part	2		32054 "Light Bluish Gray Technic, Pin Long with Friction Ridges Lengthwise and Stop Bush"	6
14.4	14	Missing	Part	2		43093 "Blue Technic, Axle Pin with Friction Ridges Lengthwise"	10
14.3		Extra	Part	2		2780 "Black Technic, Pin with Friction Ridges Lengthwise WITH Center Slots"	6
14.2		Wrong	Part	2		32184 "Black Technic, Axle and Pin Connector Perpendicular 3L with Center Pin Hole"	6
13.10	13	Wrong	Color (Visible)	1		6536 "White Technic, Axle and Pin Connector Perpendicular"	3
13.9	12	Misplacement	Deviation	1		87083 "Dark Bluish Gray Technic, Axle 4 with Stop"	3
13.6		Wrong	Part	1		32140 "Black Technic, Liftarm 2 x 4 L-Shape Thick"	3
		Extra	Part	1		32316 "Light Bluish Gray Technic, Liftarm 1 x 5 Thick"	3
13.5	11	Wrong	Part	1		42003 "Light Bluish Gray Technic, Axle and Pin Connector Perpendicular 3L with 2 Pin Holes"	3
		Wrong	Part	1		32523 "Blue Technic, Liftarm 1 x 3 Thick"	3
13.4	10	Wrong	Part	1		6558 "Blue Technic, Pin Long with Friction Ridges Lengthwise"	3
13.3		Wrong	Part	1		32140 "Black Technic, Liftarm 2 x 4 L-Shape Thick"	3
		Extra	Part	1		32316 "Light Bluish Gray Technic, Liftarm 1 x 5 Thick"	3
						Too much differences seen ahead and accumulated	

Name:	Luc Worms	55
Nickname:	Luc2000	
Country:	NL	
Submission Date / Time:	2013-11-29 / 22:16	
Submission entry order:	27	
Digital File Type	LDD	
Annotations:		

26.4	30	Missing	Part	1		4265c "Light Bluish Gray Technic Bush 1/2 Smooth"	5
26.3	29	Wrong	Part	1		32209 "Dark Bluish Gray Technic, Axle 5.5 with Stop"	3
24.8	27	Misplacement	Orientation	1		60483 "Light Bluish Gray Technic, Liftarm 1 x 2 Thick with Pin Hole and Axle Hole"	3
24.7	26	Misplacement	Orientation	1		60483 "Light Bluish Gray Technic, Liftarm 1 x 2 Thick with Pin Hole and Axle Hole"	3
14.4	14	Missing	Part	2		43093 "Blue Technic, Axle Pin with Friction Ridges Lengthwise"	10
14.3		Extra	Part	2		2780 "Black Technic, Pin with Friction Ridges Lengthwise WITH Center Slots"	6
14.2		Missing	Part	2		32184 "Black Technic, Axle and Pin Connector Perpendicular 3L with Center Pin Hole"	10
13.10	13	Wrong	Color (Visible)	1		6536 "White Technic, Axle and Pin Connector Perpendicular"	3
13.9	12	Wrong	Part	1		87083 "Dark Bluish Gray Technic, Axle 4 with Stop"	3
13.5	11	Wrong	Part	1		42003 "Light Bluish Gray Technic, Axle and Pin Connector Perpendicular 3L with 2 Pin Holes"	3
7	6	Extra	Part	1		4519 "Light Bluish Gray Technic, Axle 3"	3
6	6	Wrong	Part	1		43093 "Blue Technic, Axle Pin with Friction Ridges Lengthwise"	3

Name:	Kiwon Chang	117
Nickname:	2B1G	
Country:	KR	
Submission Date / Time:	2013-11-30 / 06:50	
Submission entry order:	28	
Digital File Type	LDD	
Annotations:		

27.1	32	Missing	Part	1		87082 "Black Technic, Pin Long with Friction Ridges Lengthwise and Center Pin Hole"	5
26.4	30	Missing	Part	1		4265c "Light Bluish Gray Technic Bush 1/2 Smooth"	5
26.3	29	Wrong	Part	1		32209 "Dark Bluish Gray Technic, Axle 5.5 with Stop"	3
26.1	28	Wrong	Part	1		87083 "Dark Bluish Gray Technic, Axle 4 with Stop"	3
24.8	27	Wrong	Part	1		60483 "Light Bluish Gray Technic, Liftarm 1 x 2 Thick with Pin Hole and Axle Hole"	3
24.7	26	Wrong	Part	1		60483 "Light Bluish Gray Technic, Liftarm 1 x 2 Thick with Pin Hole and Axle Hole"	3
24.4		Wrong	Part	1		60483 "Black Technic, Liftarm 1 x 2 Thick with Pin Hole and Axle Hole"	3
23.3	25	Wrong	Color (Invisible)	1		42003 "Red Technic, Axle 2 Notched"	2
		Extra	Part	1		32062 "Black Technic, Axle 2 Notched"	3
23.2	24	Missing	Part	1		4265c "Light Bluish Gray Technic Bush 1/2 Smooth"	5
						Black instead of Red	

Building Instructions Step	Page	Mismatch Type	Mismatch Specific	Occurrences	Color	Part mismatched	Penalties
23.1		Wrong	Part	1		32449 "White Technic, Liftarm 1 x 4 Thin"	3
22.5	23	Missing	Part	1		4265c "Light Bluish Gray Technic Bush 1/2 Smooth"	5
22.2	21	Wrong	Part	1		32449 "White Technic, Liftarm 1 x 4 Thin"	3
14.4	14	Missing	Part	2		43093 "Blue Technic, Axle Pin with Friction Ridges Lengthwise"	10
14.3		Extra	Part	2		2780 "Black Technic, Pin with Friction Ridges Lengthwise WITH Center Slots"	6
14.2		Missing	Part	2		32184 "Black Technic, Axle and Pin Connector Perpendicular 3L with Center Pin Hole"	10
13.10	13	Wrong	Color (Visible)	1		6536 "White Technic, Axle and Pin Connector Perpendicular"	3
13.9	12	Wrong	Part	1		87083 "Dark Bluish Gray Technic, Axle 4 with Stop"	3
13.4	10	Wrong	Part	1		6558 "Blue Technic, Pin Long with Friction Ridges Lengthwise"	3
9	7	Wrong	Color (Invisible)	2		6558 "Blue Technic, Pin Long with Friction Ridges Lengthwise"	4
7	6	Wrong	Part	1		32140 "Black Technic, Liftarm 2 x 4 L-Shape Thick"	3
		Extra	Part	1		6632 "Black Technic, Liftarm 1 x 3 Thin"	3
		Extra	Part	1		3705 "Black Technic, Axle 4"	3
6	6	Missing	Part	1		43093 "Blue Technic, Axle Pin with Friction Ridges Lengthwise"	5
		Missing	Part	1		32054 "Light Bluish Gray Technic, Pin Long with Friction Ridges Lengthwise and Stop Bush"	5
5	1	Wrong	Color (Invisible)	1		4519 "Light Bluish Gray Technic, Axle 3"	2
3	4	Wrong	Part	1		32526 "Light Bluish Gray Technic, Liftarm 3 x 5 L-Shape Thick"	3
2	3	Missing	Part	1		32184 "Black Technic, Axle and Pin Connector Perpendicular 3L with Center Pin Hole"	5
1		Wrong	Part	1		32526 "Light Bluish Gray Technic, Liftarm 3 x 5 L-Shape Thick"	3

Name:	Ismaël Juhoor	86
Nickname:	Khan	
Country:	FR	
Submission Date / Time:	2013-12-01 / 22:37	
Submission entry order:	30	
Digital File Type	SR 3D	
Annotations:		

26.4	30	Missing	Part	1		4265c "Light Bluish Gray Technic Bush 1/2 Smooth"	5
26.3	29	Wrong	Part	1		32209 "Dark Bluish Gray Technic, Axle 5.5 with Stop"	3
26.1	28	Wrong	Part	1		87083 "Dark Bluish Gray Technic, Axle 4 with Stop"	3
24.8	27	Misplacement	Orientation	1		60483 "Light Bluish Gray Technic, Liftarm 1 x 2 Thick with Pin Hole and Axle Hole"	3
24.7	26	Misplacement	Orientation	1		60483 "Light Bluish Gray Technic, Liftarm 1 x 2 Thick with Pin Hole and Axle Hole"	3
20.4	18	Missing	Part	1		3713 "Light Bluish Gray Technic Bush"	5
14.4	14	Missing	Part	2		43093 "Blue Technic, Axle Pin with Friction Ridges Lengthwise"	10
14.3		Extra	Part	2		2780 "Black Technic, Pin with Friction Ridges Lengthwise WITH Center Slots"	6
14.2		Wrong	Part	2		32184 "Black Technic, Axle and Pin Connector Perpendicular 3L with Center Pin Hole"	6
13.9	12	Wrong	Color (Invisible)	1		87083 "Dark Bluish Gray Technic, Axle 4 with Stop"	2
13.5	11	Wrong	Part	1		42003 "Light Bluish Gray Technic, Axle and Pin Connector Perpendicular 3L with 2 Pin Holes"	3
11	8	Extra	Part	1		32140 "Black Technic, Liftarm 2 x 4 L-Shape Thick"	3
		Extra	Part	1		6558 "Blue Technic, Pin Long with Friction Ridges Lengthwise"	3
7	6	Extra	Part	1		4519 "Light Bluish Gray Technic, Axle 3"	3
6	6	Missing	Part	1		43093 "Blue Technic, Axle Pin with Friction Ridges Lengthwise"	5
		Missing	Part	1		32054 "Light Bluish Gray Technic, Pin Long with Friction Ridges Lengthwise and Stop Bush"	5
		Extra	Part	1		6558 "Blue Technic, Pin Long with Friction Ridges Lengthwise"	3
3	4	Misplacement	Orientation	1		32526 "Light Bluish Gray Technic, Liftarm 3 x 5 L-Shape Thick"	3
2	3	Wrong	Part	1		32184 "Black Technic, Axle and Pin Connector Perpendicular 3L with Center Pin Hole"	3
		Wrong	Part	1		32073 "Light Bluish Gray Technic, Axle 5"	3
		Extra	Part	1		43093 "Blue Technic, Axle Pin with Friction Ridges Lengthwise"	3
1	3	Misplacement	Orientation	1		32526 "Light Bluish Gray Technic, Liftarm 3 x 5 L-Shape Thick"	3

Name:	Matej Pukancik	80
Nickname:	Puki	
Country:	SK	
Submission Date / Time:	2013-12-02 / 03:50	
Submission entry order:	31	
Digital File Type	LDD	
Annotations:		

26.4	30	Wrong	Part	1		4265c "Light Bluish Gray Technic Bush 1/2 Smooth"	3
26.3	29	Wrong	Part	1		32209 "Dark Bluish Gray Technic, Axle 5.5 with Stop"	3
26.1	28	Wrong	Part	1		87083 "Dark Bluish Gray Technic, Axle 4 with Stop"	3
24.8	27	Misplacement	Orientation	1		60483 "Light Bluish Gray Technic, Liftarm 1 x 2 Thick with Pin Hole and Axle Hole"	3
24.7	26	Misplacement	Orientation	1		60483 "Light Bluish Gray Technic, Liftarm 1 x 2 Thick with Pin Hole and Axle Hole"	3
20.4	18	Missing	Part	1		3713 "Light Bluish Gray Technic Bush"	5
14.4	14	Missing	Part	2		43093 "Blue Technic, Axle Pin with Friction Ridges Lengthwise"	10
14.3		Extra	Part	2		2780 "Black Technic, Pin with Friction Ridges Lengthwise WITH Center Slots"	6
14.2		Wrong	Part	2		32184 "Black Technic, Axle and Pin Connector Perpendicular 3L with Center Pin Hole"	6
13.10	13	Wrong	Color (Visible)	1		6536 "White Technic, Axle and Pin Connector Perpendicular"	3
13.9	12	Wrong	Part	1		87083 "Dark Bluish Gray Technic, Axle 4 with Stop"	3
13.5	11	Wrong	Part	1		42003 "Light Bluish Gray Technic, Axle and Pin Connector Perpendicular 3L with 2 Pin Holes"	3
13.4	10	Wrong	Part	1		6558 "Blue Technic, Pin Long with Friction Ridges Lengthwise"	3
7	6	Wrong	Part	1		32140 "Black Technic, Liftarm 2 x 4 L-Shape Thick"	3
		Extra	Part	1		6632 "Black Technic, Liftarm 1 x 3 Thin"	3
		Extra	Part	1		32062 "Red Technic, Axle 2 Notched"	3
6	6	Misplacement	Deviation & Orientation	1		43093 "Blue Technic, Axle Pin with Friction Ridges Lengthwise"	3
		Missing	Part	1		32054 "Light Bluish Gray Technic, Pin Long with Friction Ridges Lengthwise and Stop Bush"	5
5	5	Extra	Part	1		60483 "Black Technic, Liftarm 1 x 2 Thick with Pin Hole and Axle Hole"	3
		Extra	Part	1		4519 "Light Bluish Gray Technic, Axle 3"	3
2	3	Wrong	Part	1		32184 "Black Technic, Axle and Pin Connector Perpendicular 3L with Center Pin Hole"	3

Name:	Shimon Bogomolov	39
Nickname:	Shimon	
Country:	IL	
Submission Date / Time:	2013-12-02 / 14:19	
Submission entry order:	32	
Digital File Type	LDD	
Annotations:		

26.4	30	Missing	Part	1		4265c "Light Bluish Gray Technic Bush 1/2 Smooth"	5
26.3	29	Wrong	Part	1		32209 "Dark Bluish Gray Technic, Axle 5.5 with Stop"	3
24.4		Wrong	Part	1		41677 "Blue Technic, Liftarm 1 x 2 Thin"	3
		Missing	Part	1		41677 "Blue Technic, Liftarm 1 x 2 Thin"	5
14.3		Extra	Part	2		2780 "Black Technic, Pin with Friction Ridges Lengthwise WITH Center Slots"	6
13.5	11	Wrong	Part	1		42003 "Light Bluish Gray Technic, Axle and Pin Connector Perpendicular 3L with 2 Pin Holes"	3
6	6	Wrong	Part	1		43093 "Blue Technic, Axle Pin with Friction Ridges Lengthwise"	3
		Missing	Part	1		32054 "Light Bluish Gray Technic, Pin Long with Friction Ridges Lengthwise and Stop Bush"	5
2.3		Extra	Part	1		32140 "Black Technic, Liftarm 2 x 4 L-Shape Thick"	3
		Extra	Part	1		6558 "Blue Technic, Pin Long with Friction Ridges Lengthwise"	3

Name:	Kamen Daalysky	97
Nickname:	le60head	
Country:	BG	
Submission Date / Time:	2013-12-03 / 09:01	
Submission entry order:	33	
Digital File Type	LDD	
Annotations:		

26.4	30	Missing	Part	1		4265c "Light Bluish Gray Technic Bush 1/2 Smooth"	5
26.3	29	Wrong	Part	1		32209 "Dark Bluish Gray Technic, Axle 5.5 with Stop"	3
26.1	28	Wrong	Part	1		87083 "Dark Bluish Gray Technic, Axle 4 with Stop"	3
20.4	18	Missing	Part	1		3713 "Light Bluish Gray Technic Bush"	3
20.3		Wrong	Part	1		32209 "Dark Bluish Gray Technic, Axle 5.5 with Stop"	3
14.4	14	Missing	Part	2		43093 "Blue Technic, Axle Pin with Friction Ridges Lengthwise"	10
14.3		Extra	Part	2		2780 "Black Technic, Pin with Friction Ridges Lengthwise WITH Center Slots"	6
14.2		Wrong	Part	2		32184 "Black Technic, Axle and Pin Connector Perpendicular 3L with Center Pin Hole"	6

Building Instructions Step	Page	Mismatch Type	Mismatch Specific	Occurrences	Color	Part mismatched				Penalties
13.10	13	Wrong	Color (Visible)	1		6536 "White Technic, Axle and Pin Connector Perpendicular"	LBG	instead of	White	3
13.9	12	Wrong	Color (Invisible)	1		3713 "Light Bluish Gray Technic Bush"	VLBG	instead of	LBG	2
		Wrong	Part	1		87083 "Dark Bluish Gray Technic, Axle 4 with Stop"				3
13.5	11	Wrong	Part	1		42003 "Light Bluish Gray Technic, Axle and Pin Connector Perpendicular 3L with 2 Pin Holes"				3
13.4	10	Wrong	Part	1		6558 "Blue Technic, Pin Long with Friction Ridges Lengthwise"				3
7	6	Wrong	Part	2		2825 "Light Bluish Gray Technic, Liftarm 1 x 4 Thin with Stud Connector"				6
		Extra	Part	1		32062 "Red Technic, Axle 2 Notched"				3
		Misplacement	Deviation	1		32140 "Black Technic, Liftarm 2 x 4 L-Shape Thick"				3
6	6	Extra	Part	1		6558 "Blue Technic, Pin Long with Friction Ridges Lengthwise"				3
		Extra	Part	2		6536 "White Technic, Axle and Pin Connector Perpendicular"				6
		Extra	Part	2		43093 "Blue Technic, Axle Pin with Friction Ridges Lengthwise"				6
		Missing	Part	1		43093 "Blue Technic, Axle Pin with Friction Ridges Lengthwise"				5
		Missing	Part	1		32054 "Light Bluish Gray Technic, Pin Long with Friction Ridges Lengthwise and Stop Bush"				5
5	5	Missing	Part	1		4519 "Light Bluish Gray Technic, Axle 3"				5